

Стандарт	Код	Символ*	Стандарт	Код	Символ*	Стандарт	Код	Символ*	Стандарт	Код	Символ*
 IEC 5022a	02047 T	S 47	 ISO 0018	02062 T		 ISO 0353	02074 T		 02089 T		
 IEC 5022a	02046 T	S 46	 ISO 0019	02063 T		 ISO 0910	02075 T		 02090 T		
 IEC 5023a	02049 T		 ISO 0020	02064 T		 IEC 5014a	02076 T		 IEC 5177a	020135 T	
 ISO 0001	02050 T		 ISO 0021	02065 T		 UNI 3.2.1	02077 T		 ISO 0058	020136 T	
 ISO 0002	02051 T		 ISO 0026	02066 T		 IEC 5012a	02078 T		 IEC 5308a	020137 T	
 ISO 0004	02052 T		 ISO 0096	02048 T	S 48	 ISO 0028	02079 T		 IEC 5178a	020138 T	S 138
 ISO 0004	02053 T		 IEC 5007a	02043 T	S 43	 ISO 0029	02080 T		 IEC 5111a	020139 T	S 140
 ISO 0259	02054 T		 IEC 5008a	02042 T	S 42	 ISO 0030	02081 T		 IEC 5104a	020140 T	
 ISO 0266	02057 T		 IEC 5010a	02067 T	S 67	 ISO 0391	02082 T		 IEC 5009a	020141 T	
 IEC 5005a	02044 T		 IEC 5011a	02068 T	S 68	 ISO 0032	02083 T		 020142 T		
 IEC 5006a	02045 T		 ISO 0022	02069 T		 ISO 0033	02084 T		 ISO 0915	020143 T	
 ISO 0011	02058 T		 ISO 0023	02070 T		 02085 T			 IEC 5638	020144 T	S 144
 ISO 0134	02059 T		 ISO 0314	02071 T		 02086 T			 IEC 5276a  IEC 5277a	020145 T	
 UNI 4.3.7	02060 T		 IEC 5036a	02072 T		 02087 T			 020146 T		
 IEC 5022a	02061 T		 ISO 0434	02073 T		 02088 T			 ISO 0435	020147 T	
						 ISO 0085	02038 T		 IEC 5110a	020148 T	

* - символ, який додається у кінець коду пристрою для виготовлення його із зазначеним маркуванням.
Наприклад: 020PTAINK = 020PTAINK**S47**